

Britax has issued a statement on their website and is making owners of their convertible seats aware of a potentially missing screw(s)/nut(s) at the base joint connector(s). This only affects Next Generation convertible car seats manufactured between July 2010 and August 2011.

U.S. Products affected are:

- Roundabout 55
- Marathon 70
- Boulevard 70
- Boulevard 70 CS
- Advocate 70 CS

This missing screw/nut does not affect the performance or safety of the convertible seat. Technicians or seat owners with questions should go to <http://www.britaxusa.com/convertible-statement> to learn more. replacement screw(s)/nut(s) can be obtained by calling Britax customer service at 888-4BRITAX.

We have spoken at length with Sarah Tilton, Manager of Consumer Services and of the Advocacy Community at Britax. NHTSA, Transport Canada, and Britax have agreed this is neither a recall nor a product improvement campaign. Therefore, we are letting you know about the issue but will NOT be adding it to our recall list.

If you have any questions, comments, or would like to make a suggestion for our website feel free to [email us](#) or call us at 425-828-8975 or 800-BUCK-L-UP.

Sincerely,

Kathy, Sue and Jennifer
Safety Restraint Coalition